ERICSSON

Prepared (also subject responsible if other)					
ETHGASZ Gábor Szalai		No. 109 21-CNL 113 832-2 Uen			

Approved	Checked	Date	Rev	Reference
BNEWJFCABB [Julianna Rózsa]	ETHGASZ	2017-10-04	A	GASK2

MobileL3 (v13.4.0) Protocol Modules for TTCN-3 Toolset with TITAN, Product Revision Information

Contents

Prepared (also subject responsible if other)		No.		
ETHGASZ Gábor Szalai		109 21-CNL 113 832-2 Uen		
Approved	Checked	Date	Rev	Reference
BNEWJFCABB [Julianna Rózsa]	ETHGASZ	2017-10-04	A	GASK2

1 Product Revision

1.1 Product

Old Product number: CNL 113 832   R1B

New Product number: CNL 113 832   R2A

1.2 Included Parts

1.2.1 Source Code

MoibleL3_CC_Types.ttcn

MobileL3_CommonIE_Types.ttcn

MobileL3_GMM_SM_Types.ttcn

MobileL3_MM_Types.ttcn

MobileL3_RRM_Types.ttcn

MobileL3_SMS_Types.ttcn

MobileL3_SS_Types.ttcn

MobileL3_Types.ttcn

SS_DataTypes.asn

SS_EncDec.cc

SS_Errors.asn

SS_Operations.asn

SS_PDU_Defs.asn

SS_Protocol.asn

SS_Types.ttcn

1.2.2 TPD file

MobileL3_v13.4.0_CNL113832.tpd

1.2.3 GRP file

MobileL3_v13.4.0_ProtocolModule.grp

1.2.4 Documentation

1.2.4.1 Description

Document Name

MobileL3 (v13.4.0) Protocol Modules for TTCN-3 Toolset with TITAN, Description

Document Number   Revision

1551-CNL 113 832 Uen   A

1.3 Product Dependencies

This product is based on the following products or parts of products:

Product Number & Rev.   Product/File name

CNL 113 368 R9A   COMMON Protocol Modules
                               General_Types.ttcn

CNL 113 745_1 R7B   MAP Current Protocol Modules

CNL 113 369 R1D   ROSE Protocol Modules

2 Reason for Revision

2.1 Requirement Specification

None

2.2 Change Requests

2.2.1 Implemented Change Requests

CR ID   Description

2.2.2 Not implemented Change Requests

CR ID   Trouble Effect

2.3 Exemption Requests

None.

2.4 Trouble Reports

Trouble reports received until 2017-10-04

ERICSSON ⊜					
Prepared (also subject responsible if other)			No.		
ETHGASZ Gábor Szalai			109 21-CNL 113 832-2 Uen		
Approved	Checked		Date	Rev	Reference
BNEWJFCABB [Julianna Rózsa]	ETHGASZ		2017-10-04	A	GASK2

2.4.1 Implemented Trouble Reports

TR ID   Trouble Effect

#1398266   MS_Radio_Access_Capability is wrong

2.4.2 Not implemented Trouble Reports

TR ID   Trouble Effect

3 Product Changes

3.1 R1A

Initial version

3.2 R1B

TR, artf798401 has been implemented.
LENGTHTO variant has been added to type ExtendedDRXParametersTLV.

3.3 R2A

Prepared to be open source.

MS_Radio_Access_Capability is corrected.